



## Roof Condition Report

**9BSE-A - Administration Building**  
Intermountain Power Service Corporation  
850 West Brush Wellman Road  
Delta, Utah

June 2001

Brower & Associates  
Architects & Planners

1776 North State Street, - Suite 300  
Orem, Utah 84057-2025

(801) 225-8859  
Fax: (801) 225-0138

**IP12\_003947**

# Table of Contents

<b>1</b>	Introduction	
<b>2</b>	Photographs	
<b>3</b>	Section Inventory	
<b>4</b>	Visual Inspections - Originals	
<b>5</b>	Visual Inspection Reports	
<b>6</b>	Maintenance Repair & Replacement Reports	
<b>7</b>		
<b>8</b>		

## INTRODUCTION

During the months of May and June, 2001, most of roofs of the Intermountain Power Project were evaluated by Brower & Associates, Architects and Roof Consultants, with regards to the condition of their roofs. Each roof was drawn, examined, photographed and analyzed.

The data taken from each roof was entered into MicroRoofer, a program produced and maintained by the University of Illinois at Urbana for the U.S. Army Corps of Engineers. The roof history of thousands of buildings, both military and civilian, are in the data base of the program. Each year, current data is added to the data base to keep the results of the evaluations up to date.

This report is the result of the inspection and the data gathered. Enough information is now available to make sound decisions about the repair and/or replacement of each roof.

## PHOTOGRAPHS

The first section of the report is a photographic record of the current conditions of the roof. Since the roofs are very similar, no attempt was made to provide an exhaustive photo history of each building.

The enclosed photographs are provided to give the reader a look at the general layouts of the roof, showing equipment, sizes and visual descriptions of defects. The full data on defects can be found in a following section.

## SECTION INVENTORY REPORT

To evaluate the roof in comparison with the other roofs in the data base, the design and construction had to be identified. Most of the information was available through visual observations, but some information had to be assumed.

The exterior walls of the buildings are generally made of concrete tees on the lower floors and metal siding above. The structural frame is steel columns, beams and joists. The roofs are typically installed on steel joists and metal decking.

All of the roofs were originally built-up asphalt over board insulation, topped with pea gravel. Some roofs have subsequently been recovered with an EPDM single membrane or polyurethane foam (PUF).

Without the original roof specifications or a destructive roof cut, the actual insulation material cannot be determined. Therefore, the insulation was assumed to be expanded polystyrene board three inches thick and hot-mopped into place, a very common practice. When further information is available, the correct data can be entered into the data base and new reports generated. However, the conclusions and costs produced by the report should be unchanged even if a different material is found.

The data gathered is from visual inspection of the roof surface. No attempt was made to inspect the condition of the insulation. Before major repairs are started, a roof cut should be made to see the current condition of the insulation in the areas in question.

## ROOF INSPECTION WORKSHEET

Copies of the actual roof inspection drawings are included to show the size of each section of the roof and the location of equipment, access and defects. The drawing can be used to guide repairmen to the defects and compare the condition of the roof this year with subsequent years.

The defects typically include base flashings (BF), ponding (PD), roof drains (DR), surface deterioration (SP), metal caps (MC) and debris on the roof (DV). Each defect has a severity listed: low, medium or high. Defects are identified by comparing the actual on-site conditions with photographs of defects in the guidebook.

Thus, the information entered into the MicroRoofer program is consistent with all other information gathered for other projects. The results are, therefore, very subjective and do not vary from inspector to inspector.

## VISUAL INSPECTION SUMMARY

The visual inspection gives unique information about each roof section. The area, perimeter and curb measurements are listed.

The summary also gives the Roof Condition Index (RCI). The RCI is calculated by combining the Flashing Condition Index (FCI), the Membrane Condition Index (MCI) and the Insulation Condition Index (ICI). During our inspection of the roofs, we found nearly all defects were with the base flashings and little, if any, visual defects in the membrane, such as blisters, splits, slipped asphalt plies or wind scour. The MCI, subsequently, is usually 100, meaning the membrane shows no defects. As mentioned earlier, the insulation was not evaluated and also shows an ICI of 100.

The RCI is a numeric score from one to one hundred, with anything under 60 requiring immediate evaluation and attention. The program estimates the cost of maintaining the roof each year for ten years and then makes an evaluation whether the roof should be maintained or replaced. An estimate is also made to the year when the roof should be replaced, based on the history of other similar roofs. The program only includes estimates for the coming ten years.

A list of the defects is included, with the severity and quantity. The FCI has the most typical defects. The membrane has few defects so the MCI is usually 100. Since the insulation was not examined, the ICI is always 100.

## Maintenance, Repair & Replacement Analysis

With the roof drawings and the defect list, a workman can easily find the defect and correct it. The Owner also has a guide to the normal cost of the repairs.

The MR&R gives more information about the roof section, such as area and current age.

The program predicts a year for probable replacement without any repairs and another date if the suggested repairs are made.

The cost of repairs is estimated, along with the cost for replacement. The cost of repairs is compared to the cost of replacement and a recommendation is given: repair, marginal or replace. The user must consider that the recommendation is only for the particular section of the roof being reported. The overall condition of the entire roof should be evaluated before making a final decision.

The second page justifies the recommendation made. It also included design considerations that should be considered when the work is designed.

The last sheet lists the recommended corrective action for maintenance or repairs.

With the enclosed information, the Owner can sit down with the roof consultant to create a plan for roof repairs and replacements for the next ten years. An inspection schedule can be made and a structured plan formalized to assure that the roofs receive proper attention.



## Summaries

The information from each individual roof is valuable to evaluate the work to be done on each section. Planners, however, need to see an overall picture of the project to make cost projections for future budgets.

The information for each section and visual reports are provided separately. MicroRoofer makes a summary of the entire project, which is furnished in this book.

The Section Inventory Report to the entire project is included. Individual reports are contained in the report for each building.

The Maintenance, Repairs and Replacement Summary (MR&R) lists the data for the entire project. The Roof Condition Index (RCI) for each section is listed in ascending order, to show which sections should be prioritized. The report also shows the change in the RCI if the suggested repairs are made, plus an estimate of the increased life of the roof. Then a recommendation is made, whether to repair or replace the roof and the estimated remaining life of the roof section.

Next is the Inspection Schedule Report, which lists the sections that should be examined each year. The sections with the most problems and lower RCI are listed for examination more frequently, while the entire project should be reviewed every five years.

The Distress Analysis contains all of the work listed in each individual report. The cost for each type of work is listed.

Finally, a proposed 10-year program is included, to help the Owner plan for the costs of the necessary work to keep the roofs intact and the building contents protected. This budget is a starting point for the discussion between the roof consultant and the Owner to determine the exact program to meet the Owner's budget and building needs.

## Section Inventory Report

The Section Inventory Report is provided so the Owner can see the information on the entire project without going through each individual report. The same information is included in the reports for the individual buildings.

The report lists the construction characteristics of each building.

## MR&R Analysis Summary

The Maintenance, Repair and Replacement Analysis Summary for the entire project is included to provide a convenient comparison between the sections. The sections are listed in ascending order of the RCI, with the lowest numbers listed first.

The report summarizes the cost of repairs, cost of replacements, the year of replacement and the change in the RCI if the repairs are made. It also gives a recommendation if the roof is marginal, should be repaired or replace.

## Inspection Schedule Report

The Owner has a great deal of capital tied up in his buildings and their proper function. To keep the roofs in proper condition and to extend their life, the roof sections must be examined on a regular schedule by someone who is trained to identify potential problems.

MicroRoofer suggests a yearly inspection schedule, based on the Roof Condition Index (RCI) of each section. Just as a sick child requires more attention, an aging roof needs more care to allow it to give its maximum service.

A schedule of inspections is included to help the Owner make an operational plan to see each roof section when it is most advantageous. An automobile needs some maintenance every 3,000 miles and other work on 15,000 mile intervals. More expensive maintenance is scheduled at 30,000 and 60,000 miles. Similarly, the roof sections with the lowest scores should be visited more frequently. Every section should be inspected every five years and the reports redone.

The proposed inspection fees are based on a square foot cost of \$0.025 per square foot. The cost of this inspection was based on \$.04 per square foot.

The Owner can have an employee trained to make these inspections and maintain the data base. Or an outside consultant can be retained to make the yearly roof inspections and provide current reports.

## Distress Analysis

This report provides the Owner a summary of the cost of each defect or distress. The report allows the Owner to determine the cost of repairing each class of defect, such as base flashing.

If the base flashing of all of the buildings were repaired, the repairs would easily outlive the roof membrane over the rest of the roof.

The most critical defects to repair are the roof drains. From the report, \$9,584 would be required to make all of the repairs.

Using this report, the Owner can direct his repair budget to the areas that most need the work.

## 10-YEAR PROGRAM

The Ten-Year Budget Report can be invaluable to budget planners as they try to allocate funds for roof maintenance, repairs and replacement. Most Owners spend money on their roofs only when an emergency presents itself, instead of making an intelligent yearly program of roof work.

Just as an automobile requires periodic maintenance to give maximum life and service, a roof needs yearly attention to prevent small defects from becoming roofing and budget disasters.

The 10-year program gives a budget outline for all of the work that is anticipated during the next ten years. If the work is not critical, it is spread over several years, as major repair projects. Replacements are also shown, along with the cost of insulation inspection and visual inspection.

For this project, a total of \$909,000 is estimated to maintain, repair and/or replace the roofs. The Owner should note, however, that the bulk of the roofs are listed for replacement within the next twelve years so the roof budget will grow substantially after ten years.




Photo No. 1-A

The east side of the Administration Building, looking northwest. Unit One Boiler is in the background.




Photo No. 2-A

The southeast corner of the Administration Building.




Photo No. 3-A

The roof of the Administration Building, looking east from the roof of Unit One Boiler.

Photo No. 1

Roof of the Administration Building, as  
seen from the General Services Building,  
looking east.





Photo No. 2

Southwest corner of the Administration  
Building, looking southeast.



Photo No. 3

Roof walkway pads are almost completely  
destroyed by the sun.








Photo No. 4

The center of the north half of the roof, looking northwest. Note the expansion joint through the center of the photo.




Photo No. 5

The north side of the main skylight, looking west at Unit One.



Photo No. 6

The northeast corner of the roof, looking northeast at the stair tower.

Photo No. 7

The north side of the skylight, looking east  
at the stair tower.




Photo No. 8

The northeast corner of the building,  
looking northeast.




Photo No. 9

The stair tower on the east side of the  
building, looking southeast.




Photo No. 10

North parapet wall. Note the hole in the wall and the gap at the top of the counterflashing. The base flashing has been painted at all joints around the roof.




Photo No. 11

Northeast corner of the roof, looking east. Note the brace in the corner and the two holes below. The parapet is bare concrete.




Photo No. 12

East parapet wall, looking east. The stair tower is to the left of the photo. Note the concrete blocks next to the stair tower.




Photo No. 13

The southeast corner of the skylight.




Photo No. 14

The southeast corner of the roof, looking to the southeast. No crickets are present to direct the water to the roof drains.



Photo No. 15

The west area of the roof, looking west.




Photo No. 16





Photo No. 17

Equipment near the west wall of the building, looking south.



Photo No. 18

The west end of the roof, looking south.  
Note the blue berries near the expansion joint.






Photo No. 19

Television antennae on the west parapet wall, looking southwest.




Photo No. 20

Southwest corner of the roof, looking to the southeast. The equipment is shown also in Photo No. 17.




Photo No. 21

West parapet of the building, looking north. Note the blueberries in the lower center of the photo. No crickets have been installed to direct the water to the drains.

Photo No. 22

South side of the skylight, looking east.




Photo No. 23

Inside the stair tower. The roof structure has been covered with fire-retardant covering.




Photo No. 24

Counterflashing along the west wall of the stair tower. Note the gap at the top of the metal.






Photo No. 25

The joint of the expansion joint and the north parapet wall. The joint in the wall is separating.




Photo No. 26

The northwest corner of the roof, showing the steel brackets holding the panels together.




Photo No. 27

Gap in the counterflashing and a hole above the metal.






Photo No. 28

A gap in the counterflashing.




Photo No. 29

Extensive blueberries adjacent to the  
parapet wall.



Photo No. 30




Photo No. 31

Holes in the wall above the metal counter-flashing.




Photo No. 32

The roof of the stair tower, looking west.




Photo No. 33

The roof of the stair tower, looking to the northeast.



Photo No. 34

The roof of the guard building at the main entrance, looking northwest. Note the pipe inserted into the toilet stack.



Photo No. 35

A gap in the base flashing in the expansion joint.




Photo No. 36

The southwest corner of the building, looking southwest. The hose is probably condensate drainage.

Photo No. 37

The south wall of the building, with gaps in the cap metal.




Photo No. 38

Equipment near the west wall of the building, looking west.




Photo No. 39

West area of the roof. See Photo No. 19.




Photo No. 40

Equipment near the west wall. The supports under the equipment are very low.




Photo No. 41

West area of roof, looking east. Note the blueberries on either side of the expansion joint.






Photo No. 42

The skylight, showing the joint. The dark spots appear to be a growth.





ADMINISTRATION BLDG.

**Date: JUN/13/2001****Section Inventory Report****Page 1****Installation: IPP - Intermountain Power Project**

Building No.: 9BSE-A      Section: 9BSEAA      Area: 5929 Sq.Ft.  
Last Replacement:      Original Construction: 1985  
Occupancy: Office

Perimeter  
Parapet: 154 Ft.      Exp. Joint: 154 Ft.      Adj. Wall: Ft.  
Roof Edge: Ft.      Area Div.: Ft.      Other: Ft.  
Access: PENTHOUSE      Adj Roof Sec:

Structural Frame: STEEL: Bar Joists/Beams & Columns

Roof Deck: STEEL  
Slope: 1/4  
Drainage: INTERIOR DRAINS

Vapor Retarder: UNKNOWN

Insulation: EXPANDED POLYSTYRENE  
Thickness: 4 In.      Layers: 2      Tapered: N  
R-Value: 19  
Attachment: ADHESIVE - HOT

Membrane: Mfg:      Spec. No.:  
Description:  
Protected Mem.: N  
Type: BUR: Asphalt  
Attachment: FULLY ADHERED  
Reinforcement: B.U.(HOT/COLD): Glass Felt  
Surfacing: AGG: Pea Gravel  
Walkways: ASPHALT PLANK

Base Flashing: REINFORCED ASBESTOS  
Flashing Adhesive: HOT MOPPED  
Counterflashing: METAL  
Types: WALL/PARAPET

Remarks:

**IP12\_003978**



<b>Date: JUN/13/2001</b>		<b>Section Inventory Report</b>		<b>Page 2</b>	
<b>Installation: IPP - Intermountain Power Project</b>					
Building No.: 9BSE-A		Section: 9BSEAB		Area: 8235 Sq.Ft.	
Last Replacement:		Original Construction:		1985	
Occupancy: Office					
Perimeter		Exp. Joint:		Adj. Wall:	
Parapet: 218 Ft.		95 Ft.		90 Ft.	
Roof Edge: Ft.		Area Div.: Ft.		Other: Ft.	
Access: PENTHOUSE		Adj Roof Sec:			
Structural Frame:		STEEL: Bar Joists/Beams & Columns			
Roof Deck: STEEL					
Slope: 1/4					
Drainage: INTERIOR DRAINS					
Vapor Retarder:		UNKNOWN			
Insulation: EXPANDED POLYSTYRENE					
Thickness: 4 In.		Layers: 2		Tapered: N	
R-Value: 19					
Attachment: ADHESIVE - HOT					
Membrane: Mfg:		Spec. No.:			
Description:					
Protected Mem.: N					
Type: BUR: Asphalt					
Attachment: FULLY ADHERED					
Reinforcement: B.U.(HOT/COLD): Glass Felt					
Surfacing: AGG: Pea Gravel					
Walkways: ASPHALT PLANK					
Base Flashing: REINFORCED ASBESTOS					
Flashing Adhesive: HOT MOPPED					
Counterflashing: METAL					
Types: WALL/PARAPET					
Remarks:					

IP12\_003979

<b>Date: JUN/13/2001</b>		<b>Section Inventory Report</b>		<b>Page 3</b>	
<b>Installation: IPP - Intermountain Power Project</b>					
Building No.: 9BSE-A		Section: 9BSEAC		Area: 1270 Sq.Ft.	
Last Replacement: Occupancy: Offices		Original Construction:		1985	
Perimeter Parapet: 150 Ft.      Exp. Joint:      Ft.      Adj. Wall:      Ft. Roof Edge:      Ft.      Area Div.:      Ft.      Other:      Ft. Access: EXTERNAL LADDER: Temporary      Adj Roof Sec:					
Structural Frame:		STEEL: Bar Joists/Beams & Columns			
Roof Deck: STEEL					
Slope: 1/4					
Drainage: INTERIOR DRAINS					
Vapor Retarder:		UNKNOWN			
Insulation: EXPANDED POLYSTYRENE					
Thickness: 4 In.		Layers: 2		Tapered: N	
R-Value: 19					
Attachment: ADHESIVE - HOT					
Membrane: Mfg:		Spec. No.:			
Description:					
Protected Mem.: N					
Type: BUR: Asphalt					
Attachment: FULLY ADHERED					
Reinforcement: B.U.(HOT/COLD): Glass Felt					
Surfacing: AGG: Pea Gravel					
Walkways: ASPHALT PLANK					
Base Flashing: REINFORCED ASBESTOS					
Flashing Adhesive: HOT MOPPED					
Counterflashing: METAL					
Types: WALL/PARAPET					
Remarks:					

IP12\_003980

Date: JUN/13/2001

Section Inventory Report

Page 4

Installation: IPP - Intermountain Power Project

Building No.: 9BSE-A Section: 9BSEAD Area: 1476 Sq.Ft.

Last Replacement: Original Construction: 1985  
Occupancy: Office

Perimeter  
Parapet: 36 Ft. Exp. Joint: 82 Ft. Adj. Wall: 36 Ft.  
Roof Edge: Ft. Area Div.: Ft. Other: Ft.  
Access: PENTHOUSE Adj Roof Sec:

Structural Frame: STEEL: Bar Joists/Beams & Columns

Roof Deck: STEEL  
Slope: 1/4  
Drainage: INTERIOR DRAINS

Vapor Retarder: VINYL

Insulation: EXPANDED POLYSTYRENE  
Thickness: 4 In. Layers: 2 Tapered: N  
R-Value: 19  
Attachment: ADHESIVE - HOT

Membrane: Mfg: Spec. No.:  
Description:  
Protected Mem.: N  
Type: BUR: Asphalt  
Attachment: FULLY ADHERED  
Reinforcement: B.U.(HOT/COLD): Glass Felt  
Surfacing: AGG: Pea Gravel  
Walkways: ASPHALT PLANK

Base Flashing: REINFORCED ASBESTOS  
Flashing Adhesive: HOT MOPPED  
Counterflashing: METAL  
Types: WALL/PARAPET

Remarks:

IP12\_003981

Date: JUN/13/2001

## Section Inventory Report

Page 5

### Installation: IPP - Intermountain Power Project

Building No.: 9BSE-A      Section: 9BSEAE      Area: 3888 Sq.Ft.  
Last Replacement:      Original Construction: 1985  
Occupancy: Office

Perimeter  
Parapet:      Ft.      Exp. Joint:      Ft.      Adj. Wall:      Ft.  
Roof Edge: 288 Ft.      Area Div.:      Ft.      Other:      Ft.  
Access: PENTHOUSE      Adj Roof Sec:

Structural Frame: STEEL: Bar Joists/Beams & Columns

Roof Deck: STEEL  
Slope: 1/4  
Drainage: INTERIOR DRAINS

Vapor Retarder: NONE

Insulation: NONE  
Thickness:      In.      Layers:      Tapered: N  
R-Value:  
Attachment:

Membrane: Mfg:      Spec. No.:  
Description:  
Protected Mem.: N  
Type:  
Attachment:  
Reinforcement:  
Surfacing:  
Walkways:

Base Flashing:  
Flashing Adhesive:  
Counterflashing:  
Types:

Remarks: Skylight

IP12\_003982

**Date: JUN/13/2001****Section Inventory Report****Page 6****Installation: IPP - Intermountain Power Project**

Building No.: 9BSE-A      Section: 9BSEAF      Area: 1220 Sq.Ft.  
Last Replacement:      Original Construction: 1985  
Occupancy: Office

Perimeter  
Parapet: 54 Ft.      Exp. Joint: 61 Ft.      Adj. Wall: 20 Ft.  
Roof Edge: Ft.      Area Div.: Ft.      Other: Ft.  
Access: PENTHOUSE      Adj Roof Sec:

Structural Frame: STEEL: Bar Joists/Beams & Columns

Roof Deck: STEEL  
Slope: 1/4  
Drainage: INTERIOR DRAINS

Vapor Retarder: UNKNOWN

Insulation: EXPANDED POLYSTYRENE  
Thickness: 4 In.      Layers: 2      Tapered: N  
R-Value: 19  
Attachment: ADHESIVE - HOT

Membrane: Mfg:      Spec. No.:  
Description:  
Protected Mem.: N  
Type: BUR: Asphalt  
Attachment: FULLY ADHERED  
Reinforcement: B.U.(HOT/COLD): Glass Felt  
Surfacing: AGG: Pea Gravel  
Walkways: ASPHALT PLANK

Base Flashing: REINFORCED ASBESTOS  
Flashing Adhesive: HOT MOPPED  
Counterflashing: METAL  
Types: WALL/PARAPET

Remarks:

**IP12\_003983**

**Date: JUN/13/2001****Section Inventory Report****Page 7****Installation: IPP - Intermountain Power Project**

Building No.: 9BSE-A Section: 9BSEAG Area: 429 Sq.Ft.

Last Replacement:  
Occupancy: Office Original Construction: 1985Perimeter  
Parapet: 75 Ft. Exp. Joint: 32 Ft. Adj. Wall: Ft.  
Roof Edge: Ft. Area Div.: Ft. Other: Ft.  
Access: PENTHOUSE Adj Roof Sec:

Structural Frame: STEEL: Bar Joists/Beams &amp; Columns

Roof Deck: STEEL  
Slope: 1/4  
Drainage: INTERIOR DRAINS

Vapor Retarder: UNKNOWN

Insulation: EXPANDED POLYSTYRENE  
Thickness: 4 In. Layers: 2 Tapered: N  
R-Value: 19  
Attachment: ADHESIVE - HOTMembrane: Mfg: Spec. No.:  
Description:  
Protected Mem.: N  
Type: BUR: Asphalt  
Attachment: FULLY ADHERED  
Reinforcement: B.U.(HOT/COLD): Glass Felt  
Surfacing: AGG: Pea Gravel  
Walkways: ASPHALT PLANKBase Flashing: REINFORCED ASBESTOS  
Flashing Adhesive: HOT MOPPED  
Counterflashing: METAL  
Types: WALL/PARAPET

Remarks:

**IP12\_003984**

<b>Date: JUN/13/2001</b>		<b>Section Inventory Report</b>		<b>Page 8</b>	
<b>Installation: IPP - Intermountain Power Project</b>					
Building No.: 9BSE-A		Section: 9BSEAH		Area: 5929 Sq.Ft.	
Last Replacement: Occupancy: Office		Original Construction:		1985	
Perimeter Parapet: 115 Ft.		Exp. Joint: 72 Ft.		Adj. Wall: 36 Ft.	
Roof Edge: Ft.		Area Div.: Ft.		Other: Ft.	
Access: PENTHOUSE		Adj Roof Sec:			
Structural Frame:		STEEL: Bar Joists/Beams & Columns			
Roof Deck: STEEL					
Slope: 1/4					
Drainage: INTERIOR DRAINS					
Vapor Retarder:		UNKNOWN			
Insulation: EXPANDED POLYSTYRENE					
Thickness: 4 In.		Layers: 2		Tapered: N	
R-Value: 19					
Attachment:					
Membrane: Mfg:		Spec. No.:			
Description:					
Protected Mem.: N					
Type: BUR: Asphalt					
Attachment: FULLY ADHERED					
Reinforcement: B.U.(HOT/COLD): Glass Felt					
Surfacing: AGG: Pea Gravel					
Walkways: ASPHALT PLANK					
Base Flashing: REINFORCED ASBESTOS					
Flashing Adhesive: HOT MOPPED					
Counterflashing: METAL					
Types: WALL/PARAPET					
Remarks:					

IP12\_003985

<b>Date: JUN/13/2001</b>		<b>Section Inventory Report</b>		<b>Page 9</b>	
<b>Installation: IPP - Intermountain Power Project</b>					
Building No.: 9BSE-A		Section: 9BSEAI		Area: 8547 Sq.Ft.	
Last Replacement:		Original Construction:		1985	
Occupancy: Office					
Perimeter Parapet: 188 Ft.      Exp. Joint: 77 Ft.      Adj. Wall: 72 Ft. Roof Edge:      Ft.      Area Div.:      Ft.      Other:      Ft. Access: PENTHOUSE      Adj Roof Sec:					
Structural Frame:		STEEL: Bar Joists/Beams & Columns			
Roof Deck: STEEL					
Slope: 1/4					
Drainage: INTERIOR DRAINS					
Vapor Retarder:		UNKNOWN			
Insulation: EXPANDED POLYSTYRENE					
Thickness: 4 In.		Layers: 2		Tapered: N	
R-Value: 19					
Attachment: ADHESIVE - HOT					
Membrane: Mfg:		Spec. No.:			
Description:					
Protected Mem.: N					
Type: BUR: Asphalt					
Attachment: FULLY ADHERED					
Reinforcement: B.U.(HOT/COLD): Glass Felt					
Surfacing: AGG: Pea Gravel					
Walkways: ASPHALT PLANK					
Base Flashing: REINFORCED ASBESTOS					
Flashing Adhesive: HOT MOPPED					
Counterflashing: METAL					
Types: WALL/PARAPET					
Remarks:					

IP12\_003986



## Installation: IPP - Intermountain Power Project

## Selection Criteria

Building ID	9BSE-A
Category Code	All
Membrane Type	All
Insulation Type	All
Deck Type	All
Roof Slope	All
Section Area	All


## Sort Criteria

Building ID - Ascending



**IP12\_003988**

Photo No. 42

The skylight, showing the joint. The dark spots appear to be a growth.



Administration Bldg. (3)



[illegible]



[illegible]

[illegible]





[illegible]

[illegible]



[illegible]
$$\begin{array}{r} 222 \\ 154 \\ \hline 376 \end{array}$$

L-1017-d-2

62

**Installation: IPP - Intermountain Power Project**

Date Inspected: 05/17/2001

Building: 9BSE-A - Administration Building

Section: 9BSEAA - Administration - A

Category Code: 61021      Administrative Facilities  
 Administrative Buildings  
 Engineer Administration Building

Roof Section Area: 5929 SqFt

Flashing Length: 308 Ft      Perimeter: 308 Ft      Curb: 0 Ft

FCI of Section: 50

Rating: Fair

MCI of Section: 88

Rating: Excellent

ICI of Section: None

Rating: None

RCI of Section: 63

Rating: MODERATE REPAIRS NEEDED

## Flashing Distresses

Distress Type	Severity	Quantity	Density	Deduct
BF BASE FLASHING	H	4	1.30	9.8
BF BASE FLASHING	M	308	100.00	50.3
BF BASE FLASHING	L	616	200.00	20.1
DR DRAIN & SCUPPER	M	2	0.65	14.2
MC METAL CAP	M	60	19.48	17.1
MC METAL CAP	L	10	3.25	5.1

## Membrane Distresses

Distress Type	Severity	Quantity	Density	Deduct
PD PONDING	L	308	5.19	12.2

## Installation: IPP - Intermountain Power Project

Date Inspected: 05/17/2001

Building: 9BSE-A - Administration Building

Section: 9BSEAB - Administration - B

Category Code: 61021      Administrative Facilities  
                                 Administrative Buildings  
                                 Engineer Administration Building

Roof Section Area: 8235 SqFt

Flashing Length: 400 Ft      Perimeter: 172 Ft      Curb: 228 Ft

FCI of Section: 50      Rating: Fair

MCI of Section: 100      Rating: Excellent

ICI of Section: None      Rating: None

RCI of Section: 65      Rating: MODERATE REPAIRS NEEDED

## Flashing Distresses

Distress Type	Severity	Quantity	Density	Deduct
BF BASE FLASHING	H	2	0.50	6.7
BF BASE FLASHING	M	400	100.00	50.3
BF BASE FLASHING	L	800	200.00	20.1
DR DRAIN & SCUPPER	M	2	0.50	12.1
MC METAL CAP	M	20	5.00	12.1
MC METAL CAP	L	10	2.50	4.4

## Membrane Distresses

Distress Type	Severity	Quantity	Density	Deduct
None				

## Installation: IPP - Intermountain Power Project

Date Inspected: 05/17/2001

Building: 9BSE-A - Administration Building

Section: 9BSEAC - Administration - C

Category Code: 61021      Administrative Facilities  
 Administrative Buildings  
 Engineer Administration Building

Roof Section Area: 1270 SqFt

Flashing Length: 166 Ft      Perimeter: 150 Ft      Curb: 16 Ft

FCI of Section: 50

Rating: Fair

MCI of Section: 73

Rating: Very Good

ICI of Section: None

Rating: None

RCI of Section: 61

Rating: MODERATE REPAIRS NEEDED

## Flashing Distresses

Distress Type	Severity	Quantity	Density	Deduct
BF BASE FLASHING	H	2	1.20	9.4
BF BASE FLASHING	M	166	100.00	50.3
BF BASE FLASHING	L	332	200.00	20.1
DR DRAIN & SCUPPER	M	1	0.60	13.6
MC METAL CAP	M	25	15.06	16.1

## Membrane Distresses

Distress Type	Severity	Quantity	Density	Deduct
PD PONDING	L	200	15.75	26.0
SR SURFACE DET	M	16	1.26	11.6



<b>Date: JUN/27/2001</b>	<b>Visual Inspection Summary</b>	<b>Page 1</b>																																			
<b>Installation: IPP - Intermountain Power Project</b>																																					
<div style="margin-bottom: 10px;"> Date Inspected: 05/17/2001  Building: 9BSE-A - Administration Building  Section: 9BSEAD - Administration - D    Category Code: 61021      Administrative Facilities     Administrative Buildings     Engineer Administration Building </div> <div style="margin-bottom: 10px;"> Roof Section Area: 1476 SqFt </div> <div style="margin-bottom: 10px;"> Flashing Length: 154 Ft      Perimeter: 36 Ft      Curb: 118 Ft </div> <div style="margin-bottom: 10px;"> FCI of Section: 50      Rating: Fair  MCI of Section: 81      Rating: Very Good  ICI of Section: None      Rating: None    RCI of Section: 62      Rating: MODERATE REPAIRS NEEDED </div> <div> <p>Flashing Distresses</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">Distress Type</th> <th style="text-align: center;">Severity</th> <th style="text-align: center;">Quantity</th> <th style="text-align: center;">Density</th> <th style="text-align: center;">Deduct</th> </tr> </thead> <tbody> <tr> <td>BF BASE FLASHING</td> <td style="text-align: center;">M</td> <td style="text-align: center;">154</td> <td style="text-align: center;">100.00</td> <td style="text-align: center;">50.3</td> </tr> <tr> <td>BF BASE FLASHING</td> <td style="text-align: center;">L</td> <td style="text-align: center;">308</td> <td style="text-align: center;">200.00</td> <td style="text-align: center;">20.1</td> </tr> <tr> <td>DR DRAIN &amp; SCUPPER</td> <td style="text-align: center;">M</td> <td style="text-align: center;">1</td> <td style="text-align: center;">0.65</td> <td style="text-align: center;">14.2</td> </tr> <tr> <td>MC METAL CAP</td> <td style="text-align: center;">M</td> <td style="text-align: center;">10</td> <td style="text-align: center;">6.49</td> <td style="text-align: center;">13.0</td> </tr> </tbody> </table>   <p>Membrane Distresses</p> <table style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left;">Distress Type</th> <th style="text-align: center;">Severity</th> <th style="text-align: center;">Quantity</th> <th style="text-align: center;">Density</th> <th style="text-align: center;">Deduct</th> </tr> </thead> <tbody> <tr> <td>PD PONDING</td> <td style="text-align: center;">L</td> <td style="text-align: center;">144</td> <td style="text-align: center;">9.76</td> <td style="text-align: center;">19.0</td> </tr> </tbody> </table> </div>			Distress Type	Severity	Quantity	Density	Deduct	BF BASE FLASHING	M	154	100.00	50.3	BF BASE FLASHING	L	308	200.00	20.1	DR DRAIN & SCUPPER	M	1	0.65	14.2	MC METAL CAP	M	10	6.49	13.0	Distress Type	Severity	Quantity	Density	Deduct	PD PONDING	L	144	9.76	19.0
Distress Type	Severity	Quantity	Density	Deduct																																	
BF BASE FLASHING	M	154	100.00	50.3																																	
BF BASE FLASHING	L	308	200.00	20.1																																	
DR DRAIN & SCUPPER	M	1	0.65	14.2																																	
MC METAL CAP	M	10	6.49	13.0																																	
Distress Type	Severity	Quantity	Density	Deduct																																	
PD PONDING	L	144	9.76	19.0																																	

## Installation: IPP - Intermountain Power Project

Date Inspected: 05/17/2001

Building: 9BSE-A - Administration Building

Section: 9BSEAF - Administration - F

Category Code: 61021      Administrative Facilities  
                                 Administrative Buildings  
                                 Engineer Administration Building

Roof Section Area: 1220 SqFt

Flashing Length: 152 Ft      Perimeter: 56 Ft      Curb: 96 Ft

FCI of Section: 50

Rating: Fair

MCI of Section: 98

Rating: Excellent

ICI of Section: None

Rating: None

RCI of Section: 65

Rating: MODERATE REPAIRS NEEDED

## Flashing Distresses

Distress Type	Severity	Quantity	Density	Deduct
BF    BASE FLASHING	M	152	100.00	50.3
BF    BASE FLASHING	L	304	200.00	20.1
DR    DRAIN & SCUPPER	M	1	0.66	14.3
MC    METAL CAP	M	5	3.29	10.6

## Membrane Distresses

Distress Type	Severity	Quantity	Density	Deduct
DV    DEBRIS & VEG	M	10	0.82	2.2

<b>Date:</b> JUN/27/2001	<b>Visual Inspection Summary</b>	<b>Page 1</b>																																								
<b>Installation: IPP - Intermountain Power Project</b>																																										
<div style="display: flex; justify-content: space-between;"> <div> <p>Date Inspected: 05/17/2001</p> <p>Building: 9BSE-A - Administration Building</p> <p>Section: 9BSEAG - Administration - G</p> </div> <div> <p>Category Code: 61021     Administrative Facilities  Administrative Buildings  Engineer Administration Building</p> </div> </div> <div style="margin-top: 10px;"> <p>Roof Section Area: 429 SqFt</p> </div> <div style="margin-top: 10px; display: flex; justify-content: space-between;"> <div> <p>Flashing Length: 100 Ft</p> <p>FCI of Section: 50</p> <p>MCI of Section: 66</p> <p>ICI of Section: None</p> <p>RCI of Section: 60</p> </div> <div> <p>Perimeter: 64 Ft</p> <p>Rating: Fair</p> <p>Rating: Good</p> <p>Rating: None</p> <p>Rating: MODERATE REPAIRS NEEDED</p> </div> <div> <p>Curb: 36 Ft</p> </div> </div> <div style="margin-top: 10px;"> <p>Flashing Distresses</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 40%;">Distress Type</th> <th style="width: 10%;">Severity</th> <th style="width: 10%;">Quantity</th> <th style="width: 15%;">Density</th> <th style="width: 25%;">Deduct</th> </tr> </thead> <tbody> <tr> <td>BF BASE FLASHING</td> <td>M</td> <td>100</td> <td>100.00</td> <td>50.3</td> </tr> <tr> <td>BF BASE FLASHING</td> <td>L</td> <td>200</td> <td>200.00</td> <td>20.1</td> </tr> <tr> <td>DR DRAIN &amp; SCUPPER</td> <td>M</td> <td>1</td> <td>1.00</td> <td>17.5</td> </tr> <tr> <td>MC METAL CAP</td> <td>M</td> <td>5</td> <td>5.00</td> <td>12.1</td> </tr> </tbody> </table> </div> <div style="margin-top: 10px;"> <p>Membrane Distresses</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="width: 40%;">Distress Type</th> <th style="width: 10%;">Severity</th> <th style="width: 10%;">Quantity</th> <th style="width: 15%;">Density</th> <th style="width: 25%;">Deduct</th> </tr> </thead> <tbody> <tr> <td>PD PONDING</td> <td>L</td> <td>100</td> <td>23.31</td> <td>33.2</td> </tr> <tr> <td>SR SURFACE DET</td> <td>M</td> <td>25</td> <td>5.83</td> <td>16.0</td> </tr> </tbody> </table> </div>			Distress Type	Severity	Quantity	Density	Deduct	BF BASE FLASHING	M	100	100.00	50.3	BF BASE FLASHING	L	200	200.00	20.1	DR DRAIN & SCUPPER	M	1	1.00	17.5	MC METAL CAP	M	5	5.00	12.1	Distress Type	Severity	Quantity	Density	Deduct	PD PONDING	L	100	23.31	33.2	SR SURFACE DET	M	25	5.83	16.0
Distress Type	Severity	Quantity	Density	Deduct																																						
BF BASE FLASHING	M	100	100.00	50.3																																						
BF BASE FLASHING	L	200	200.00	20.1																																						
DR DRAIN & SCUPPER	M	1	1.00	17.5																																						
MC METAL CAP	M	5	5.00	12.1																																						
Distress Type	Severity	Quantity	Density	Deduct																																						
PD PONDING	L	100	23.31	33.2																																						
SR SURFACE DET	M	25	5.83	16.0																																						

## Installation: IPP - Intermountain Power Project

Date Inspected: 05/17/2001

Building: 9BSE-A - Administration Building

Section: 9BSEAH - Administration - H

Category Code: 61021      Administrative Facilities  
                                 Administrative Buildings  
                                 Engineer Administration Building

Roof Section Area: 5929 SqFt

Flashing Length: 356 Ft      Perimeter: 107 Ft      Curb: 249 Ft

FCI of Section: 50      Rating: Fair

MCI of Section: 94      Rating: Excellent

ICI of Section: None      Rating: None

RCI of Section: 64      Rating: MODERATE REPAIRS NEEDED

## Flashing Distresses

Distress Type	Severity	Quantity	Density	Deduct
BF    BASE FLASHING	H	5	1.40	10.2
BF    BASE FLASHING	M	356	100.00	50.3
BF    BASE FLASHING	L	712	200.00	20.1
DR    DRAIN & SCUPPER	M	2	0.56	13.0
MC    METAL CAP	M	15	4.21	11.4

## Membrane Distresses

Distress Type	Severity	Quantity	Density	Deduct
PD    PONDING	L	120	2.02	6.2

## Installation: IPP - Intermountain Power Project

Date Inspected: 05/17/2001

Building: 9BSE-A - Administration Building

Section: 9BSEAI - Administration - I

Category Code: 61021      Administrative Facilities  
                                 Administrative Buildings  
                                 Engineer Administration Building

Roof Section Area: 8547 SqFt

Flashing Length: 376 Ft      Perimeter: 188 Ft      Curb: 188 Ft

FCI of Section: 50      Rating: Fair

MCI of Section: 89      Rating: Excellent

ICI of Section: None      Rating: None

RCI of Section: 63      Rating: MODERATE REPAIRS NEEDED

## Flashing Distresses

Distress Type	Severity	Quantity	Density	Deduct
BF    BASE FLASHING	H	4	1.06	8.9
BF    BASE FLASHING	M	376	100.00	50.3
BF    BASE FLASHING	L	752	200.00	20.1
DR    DRAIN & SCUPPER	M	2	0.53	12.6
MC    METAL CAP	M	50	13.30	15.7

## Membrane Distresses

Distress Type	Severity	Quantity	Density	Deduct
PD    PONDING	L	400	4.68	11.4

# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAA  
 Section Area: 5929

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2006				
Additional Service Life (w/repairs):	5	Year(s)			
Predicted Year of Replacement (w/repairs):	2011				
			ICI	Current	Improved
			FCI	100	100
			MCI	50	80
Cost for Repairs:	\$ 3214.00	642.80 \$/year	RCI	88	88
Cost for Replacement:	\$ 31127.25	1556.00 \$/year		63	84

Adjusted Repair/Replace Ratio = 0.57

Recommendation: Repair

## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAA	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	5929
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 31127.25

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2006

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAA	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	5929
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 3214.00

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
308 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
4. BF-H-1  
4 LF Repair damaged base flashing by overlaying each localized defect with new base flashing. [4]
6. DR-M-1  
2 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [6]
7. MC-M-2  
60 LF Reseal failed joints in metal coping cap and reattach. [7]



**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAA

Area: 5929 SF

Age: 16

Total Repair Costs \$ 3214  
Additional Service Life 5 Yrs

Replacement Cost @ 5.25 SF \$ 31127

Total Repair Cost/ \$ 642.80 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 1556 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 0.41$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 0.57$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69		
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09		
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004011

Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAA

Area: 5929 SF

Age: 16

Flashing	Unit Cost	Qty	Total Cost		DIS-SL-DF	Unit Cost	Qty	Total Cost
DIS-SL-DF								
BF-H-1	23.37	4	\$ 93.48					
BF-H-2	9.97							
BF-H-3	30.69							
BF-M-1	4.72							
BF-M-2	4.78	308	\$ 1472.24					
BF-M-3	5.88							
BF-M-4	19.03							
DR-H-1	27.51							
DR-H-2	51.45							
DR-H-3	47.43							
DR-H-4	102.21							
DR-M-1	21.98	2	\$ 43.96					
DR-M-2	34.20							
DR-M-3	19.54							
EM-H-1	6.63							
EM-H-2	8.56							
EM-H-3	14.60							
EM-H-4	7.63							
EM-H-5	21.16							
EM-M-2	6.46							
EM-M-3	6.68							
EM-M-4	6.80							
FP-H-1	16.82							
FP-H-2	47.26							
FP-H-3	82.84							
FP-H-4	22.88							
FP-M-1	4.81							
FP-M-2	5.78							
FP-M-3	31.07							
FP-M-4	19.54							
MC-H-1	9.50							
MC-H-2	9.44							
MC-H-3	5.37							
MC-M-1	15.41							
MC-M-2	18.19	60	\$ 1091.40					
MC-M-3	8.11							
MC-M-4	4.00							
MC-M-5	6.63							
PP-H-1	19.54							
PP-H-2	37.47							
PP-H-3	21.98							
PP-H-4	51.69							
Insulation:					Repair SetUp Charge =			
	0.00		NONE				\$	514

IP12\_004012

# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAB  
 Section Area: 8235

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2007				
Additional Service Life (w/repairs):	5 Year(s)			Current	Improved
Predicted Year of Replacement (w/repairs):	2012			ICI	100
				FCI	50
Cost for Repairs:	\$ 2881.00	576.20	\$/year	MCI	100
Cost for Replacement:	\$ 43233.75	2162.00	\$/year	RCI	65
					86

Adjusted Repair/Replace Ratio = 0.43      Recommendation: Repair

## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAB	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	8235
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 43233.75

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2007

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAB	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	8235
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 2881.00

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
400 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
4. BF-H-1  
2 LF Repair damaged base flashing by overlaying each localized defect with new base flashing. [4]
5. DR-M-1  
2 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [5]
6. MC-M-2  
20 LF Reseal failed joints in metal coping cap and reattach. [6]

**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAB

Area: 8235 SF

Age: 16

Total Repair Costs \$ 2881  
Additional Service Life 5 Yrs

Replacement Cost @ 5.25 SF \$ 43234

Total Repair Cost/ \$ 576.20 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 2162 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 0.27$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 0.43$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69		
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09		
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004016

Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAB

Area: 8235 SF

Age: 16

Flashing							
DIS-SL-DF	Unit Cost	Qty	Total Cost	DIS-SL-DF	Unit Cost	Qty	Total Cost
BF-H-1	23.37	2	\$ 46.74				
BF-H-2	9.97						
BF-H-3	30.69						
BF-M-1	4.72						
BF-M-2	4.78	400	\$ 1912.00				
BF-M-3	5.88						
BF-M-4	19.03						
DR-H-1	27.51						
DR-H-2	51.45						
DR-H-3	47.43						
DR-H-4	102.21						
DR-M-1	21.98	2	\$ 43.96				
DR-M-2	34.20						
DR-M-3	19.54						
EM-H-1	6.63						
EM-H-2	8.56						
EM-H-3	14.60						
EM-H-4	7.63						
EM-H-5	21.16						
EM-M-2	6.46						
EM-M-3	6.68						
EM-M-4	6.80						
FP-H-1	16.82						
FP-H-2	47.26						
FP-H-3	82.84						
FP-H-4	22.88						
FP-M-1	4.81						
FP-M-2	5.78						
FP-M-3	31.07						
FP-M-4	19.54						
MC-H-1	9.50						
MC-H-2	9.44						
MC-H-3	5.37						
MC-M-1	15.41						
MC-M-2	18.19	20	\$ 363.80				
MC-M-3	8.11						
MC-M-4	4.00						
MC-M-5	6.63						
PP-H-1	19.54						
PP-H-2	37.47						
PP-H-3	21.98						
PP-H-4	51.69						
Insulation:				Repair SetUp Charge =			
	0.00		NONE				\$ 514

IP12\_004017

# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAC  
 Section Area: 1270

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2006					
Additional Service Life (w/repairs):	4	Year(s)			Current	Improved
Predicted Year of Replacement (w/repairs):	2010			ICI	100	100
				FCI	50	80
Cost for Repairs:	\$	1864.00	466.00	\$/year	MCI	73
Cost for Replacement:	\$	6667.50	333.00	\$/year	RCI	61
						79

Adjusted Repair/Replace Ratio = 1.56

Recommendation: Replace



## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAC	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	1270
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 6667.50

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2006

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAC	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	1270
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 1864.00

**CORRECTIVE ACTION RECOMMENDED:** Maintenance, Repair and/or Partial Replacement

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
166 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
4. BF-H-1  
2 LF Repair damaged base flashing by overlaying each localized defect with new base flashing. [4]
5. SR-M-1  
16 SF Reinstall aggregate on exposed membrane surfaces. [5]
7. DR-M-1  
1 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [7]
8. MC-M-2  
25 LF Reseal failed joints in metal coping cap and reattach. [8]

**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAC

Area: 1270 SF

Age: 16

Total Repair Costs \$ 1864  
Additional Service Life 4 Yrs

Replacement Cost @ 5.25 SF \$ 6668

Total Repair Cost/ \$ 466.00 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 333 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 1.40$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 1.56$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69		
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09	16	\$ 33.44
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004021

Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAC

Area: 1270 SF

Age: 16

Flashing

DIS-SL-DF	Unit Cost	Qty	Total Cost
BF-H-1	23.37	2	\$ 46.74
BF-H-2	9.97		
BF-H-3	30.69		
BF-M-1	4.72		
BF-M-2	4.78	166	\$ 793.48
BF-M-3	5.88		
BF-M-4	19.03		
DR-H-1	27.51		
DR-H-2	51.45		
DR-H-3	47.43		
DR-H-4	102.21		
DR-M-1	21.98	1	\$ 21.98
DR-M-2	34.20		
DR-M-3	19.54		
EM-H-1	6.63		
EM-H-2	8.56		
EM-H-3	14.60		
EM-H-4	7.63		
EM-H-5	21.16		
EM-M-2	6.46		
EM-M-3	6.68		
EM-M-4	6.80		
FP-H-1	16.82		
FP-H-2	47.26		
FP-H-3	82.84		
FP-H-4	22.88		
FP-M-1	4.81		
FP-M-2	5.78		
FP-M-3	31.07		
FP-M-4	19.54		
MC-H-1	9.50		
MC-H-2	9.44		
MC-H-3	5.37		
MC-M-1	15.41		
MC-M-2	18.19	25	\$ 454.75
MC-M-3	8.11		
MC-M-4	4.00		
MC-M-5	6.63		
PP-H-1	19.54		
PP-H-2	37.47		
PP-H-3	21.98		
PP-H-4	51.69		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	-----------	-----	------------

Insulation:

0.00

NONE

Repair SetUp Charge =

\$

514

IP12\_004022

# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAD  
 Section Area: 1476

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2006					
Additional Service Life (w/repairs):	5 Year(s)				Current	Improved
Predicted Year of Replacement (w/repairs):	2011			ICI	100	100
				FCI	50	80
Cost for Repairs:	\$ 1454.00	290.80	\$/year	MCI	81	81
Cost for Replacement:	\$ 7749.00	387.00	\$/year	RCI	62	83

Adjusted Repair/Replace Ratio = 0.91

Recommendation: Marginal

## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAD	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	1476
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	VINYL	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 7749.00

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2006

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAD	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	1476
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	VINYL	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 1454.00

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
154 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
5. DR-M-1  
1 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [5]
6. MC-M-2  
10 LF Reseal failed joints in metal coping cap and reattach. [6]

**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAD

Area: 1476 SF

Age: 16

Total Repair Costs \$ 1454  
Additional Service Life 5 Yrs

Replacement Cost @ 5.25 SF \$ 7749

Total Repair Cost/ \$ 290.80 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 387 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 0.75$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 0.91$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69		
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09		
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004026



Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAD

Area: 1476 SF

Age: 16

Flashing

DIS-SL-DF	Unit Cost	Qty	Total Cost
BF-H-1	23.37		
BF-H-2	9.97		
BF-H-3	30.69		
BF-M-1	4.72		
BF-M-2	4.78	154	\$ 736.12
BF-M-3	5.88		
BF-M-4	19.03		
DR-H-1	27.51		
DR-H-2	51.45		
DR-H-3	47.43		
DR-H-4	102.21		
DR-M-1	21.98	1	\$ 21.98
DR-M-2	34.20		
DR-M-3	19.54		
EM-H-1	6.63		
EM-H-2	8.56		
EM-H-3	14.60		
EM-H-4	7.63		
EM-H-5	21.16		
EM-M-2	6.46		
EM-M-3	6.68		
EM-M-4	6.80		
FP-H-1	16.82		
FP-H-2	47.26		
FP-H-3	82.84		
FP-H-4	22.88		
FP-M-1	4.81		
FP-M-2	5.78		
FP-M-3	31.07		
FP-M-4	19.54		
MC-H-1	9.50		
MC-H-2	9.44		
MC-H-3	5.37		
MC-M-1	15.41		
MC-M-2	18.19	10	\$ 181.90
MC-M-3	8.11		
MC-M-4	4.00		
MC-M-5	6.63		
PP-H-1	19.54		
PP-H-2	37.47		
PP-H-3	21.98		
PP-H-4	51.69		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	-----------	-----	------------

Insulation:

0.00

NONE

Repair SetUp Charge =

\$

514

IP12\_004027

# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAF  
 Section Area: 1220

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2007				
Additional Service Life (w/repairs):	5 Year(s)				
Predicted Year of Replacement (w/repairs):	2012				
				ICI	Current Improved
				FCI	100 80
Cost for Repairs:	\$ 1411.00	282.20 \$/year		MCI	98 100
Cost for Replacement:	\$ 6405.00	320.00 \$/year		RCI	65 86

Adjusted Repair/Replace Ratio = 1.04

Recommendation: Marginal

## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAF	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	1220
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 6405.00

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2007

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAF	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	1220
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 1411.00

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
152 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
4. DR-M-1  
1 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [4]
5. MC-M-2  
5 LF Reseal failed joints in metal coping cap and reattach. [5]
6. DV-M-1  
10 SF Remove foreign objects from roof. [6]

**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAF

Area: 1220 SF

Age: 16

Total Repair Costs \$ 1411  
Additional Service Life 5 Yrs

Replacement Cost @ 5.25 SF \$ 6405

Total Repair Cost/ \$ 282.20 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 320 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 0.88$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 1.04$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69	10	\$ 56.90
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09		
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004031

Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAF

Area: 1220 SF

Age: 16

Flashing

DIS-SL-DF	Unit Cost	Qty	Total Cost
BF-H-1	23.37		
BF-H-2	9.97		
BF-H-3	30.69		
BF-M-1	4.72		
BF-M-2	4.78	152	\$ 726.56
BF-M-3	5.88		
BF-M-4	19.03		
DR-H-1	27.51		
DR-H-2	51.45		
DR-H-3	47.43		
DR-H-4	102.21		
DR-M-1	21.98	1	\$ 21.98
DR-M-2	34.20		
DR-M-3	19.54		
EM-H-1	6.63		
EM-H-2	8.56		
EM-H-3	14.60		
EM-H-4	7.63		
EM-H-5	21.16		
EM-M-2	6.46		
EM-M-3	6.68		
EM-M-4	6.80		
FP-H-1	16.82		
FP-H-2	47.26		
FP-H-3	82.84		
FP-H-4	22.88		
FP-M-1	4.81		
FP-M-2	5.78		
FP-M-3	31.07		
FP-M-4	19.54		
MC-H-1	9.50		
MC-H-2	9.44		
MC-H-3	5.37		
MC-M-1	15.41		
MC-M-2	18.19	5	\$ 90.95
MC-M-3	8.11		
MC-M-4	4.00		
MC-M-5	6.63		
PP-H-1	19.54		
PP-H-2	37.47		
PP-H-3	21.98		
PP-H-4	51.69		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	-----------	-----	------------

Insulation:

0.00

NONE

Repair SetUp Charge =

\$

514

IP12\_004032

# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAG  
 Section Area: 429

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2006					
Additional Service Life (w/repairs):	3 Year(s)				Current	Improved
Predicted Year of Replacement (w/repairs):	2009				100	100
					FCI	80
Cost for Repairs:	\$ 1157.00	385.67	\$/year		MCI	67
Cost for Replacement:	\$ 2252.25	113.00	\$/year		RCI	74

Adjusted Repair/Replace Ratio = 3.58

Recommendation: Replace

## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAG	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	429
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 2252.25

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2006

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.



## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAG	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	429
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 1157.00

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
100 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
5. SR-M-1  
25 SF Reinstall aggregate on exposed membrane surfaces. [5]
6. DR-M-1  
1 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [6]
7. MC-M-2  
5 LF Reseal failed joints in metal coping cap and reattach. [7]

**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAG

Area: 429 SF

Age: 16

Total Repair Costs \$ 1157  
Additional Service Life 3 Yrs

Replacement Cost @ 5.25 SF \$ 2252

Total Repair Cost/ \$ 385.67 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 113 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 3.42$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 3.58$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69		
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09	25	\$ 52.25
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004036

Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAG

Area: 429 SF

Age: 16

Flashing

DIS-SL-DF	Unit Cost	Qty	Total Cost
BF-H-1	23.37		
BF-H-2	9.97		
BF-H-3	30.69		
BF-M-1	4.72		
BF-M-2	4.78	100	\$ 478.00
BF-M-3	5.88		
BF-M-4	19.03		
DR-H-1	27.51		
DR-H-2	51.45		
DR-H-3	47.43		
DR-H-4	102.21		
DR-M-1	21.98	1	\$ 21.98
DR-M-2	34.20		
DR-M-3	19.54		
EM-H-1	6.63		
EM-H-2	8.56		
EM-H-3	14.60		
EM-H-4	7.63		
EM-H-5	21.16		
EM-M-2	6.46		
EM-M-3	6.68		
EM-M-4	6.80		
FP-H-1	16.82		
FP-H-2	47.26		
FP-H-3	82.84		
FP-H-4	22.88		
FP-M-1	4.81		
FP-M-2	5.78		
FP-M-3	31.07		
FP-M-4	19.54		
MC-H-1	9.50		
MC-H-2	9.44		
MC-H-3	5.37		
MC-M-1	15.41		
MC-M-2	18.19	5	\$ 90.95
MC-M-3	8.11		
MC-M-4	4.00		
MC-M-5	6.63		
PP-H-1	19.54		
PP-H-2	37.47		
PP-H-3	21.98		
PP-H-4	51.69		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

Insulation:

0.00

NONE

Repair SetUp Charge =

\$

514

IP12\_004037

# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAG  
 Section Area: 429

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2006					
Additional Service Life (w/repairs):	3 Year(s)				Current	Improved
Predicted Year of Replacement (w/repairs):	2009			ICI	100	100
				FCI	50	80
Cost for Repairs:	\$ 1157.00	385.67	\$/year	MCI	66	67
Cost for Replacement:	\$ 2252.25	113.00	\$/year	RCI	60	74

Adjusted Repair/Replace Ratio = 3.58

Recommendation: Replace

## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAG	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	429
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 2252.25

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2006

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAG	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	429
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 1157.00

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
100 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
5. SR-M-1  
25 SF Reinstall aggregate on exposed membrane surfaces. [5]
6. DR-M-1  
1 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [6]
7. MC-M-2  
5 LF Reseal failed joints in metal coping cap and reattach. [7]

**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAG

Area: 429 SF

Age: 16

Total Repair Costs \$ 1157  
Additional Service Life 3 Yrs

Replacement Cost @ 5.25 SF \$ 2252

Total Repair Cost/ \$ 385.67 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 113 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 3.42$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 3.58$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69		
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09	25	\$ 52.25
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004041

Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAG

Area: 429 SF

Age: 16

Flashing							
DIS-SL-DF	Unit Cost	Qty	Total Cost	DIS-SL-DF	Unit Cost	Qty	Total Cost
BF-H-1	23.37						
BF-H-2	9.97						
BF-H-3	30.69						
BF-M-1	4.72						
BF-M-2	4.78	100	\$ 478.00				
BF-M-3	5.88						
BF-M-4	19.03						
DR-H-1	27.51						
DR-H-2	51.45						
DR-H-3	47.43						
DR-H-4	102.21						
DR-M-1	21.98	1	\$ 21.98				
DR-M-2	34.20						
DR-M-3	19.54						
EM-H-1	6.63						
EM-H-2	8.56						
EM-H-3	14.60						
EM-H-4	7.63						
EM-H-5	21.16						
EM-M-2	6.46						
EM-M-3	6.68						
EM-M-4	6.80						
FP-H-1	16.82						
FP-H-2	47.26						
FP-H-3	82.84						
FP-H-4	22.88						
FP-M-1	4.81						
FP-M-2	5.78						
FP-M-3	31.07						
FP-M-4	19.54						
MC-H-1	9.50						
MC-H-2	9.44						
MC-H-3	5.37						
MC-M-1	15.41						
MC-M-2	18.19	5	\$ 90.95				
MC-M-3	8.11						
MC-M-4	4.00						
MC-M-5	6.63						
PP-H-1	19.54						
PP-H-2	37.47						
PP-H-3	21.98						
PP-H-4	51.69						
Insulation:	0.00	NONE		Repair SetUp Charge =	\$	514	

IP12\_004042



# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAH  
 Section Area: 5929

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2006				
Additional Service Life (w/repairs):	6 Year(s)			Current	Improved
Predicted Year of Replacement (w/repairs):	2012			ICI	100
				FCI	50
Cost for Repairs:	\$ 2650.00	441.67	\$/year	MCI	94
Cost for Replacement:	\$ 31127.25	1556.00	\$/year	RCI	64
					85

Adjusted Repair/Replace Ratio = 0.44

Recommendation: Repair

## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAH	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	5929
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 31127.25

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2006

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAH	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	5929
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 2650.00

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
356 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
4. BF-H-1  
5 LF Repair damaged base flashing by overlaying each localized defect with new base flashing. [4]
5. DR-M-1  
2 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [5]
7. MC-M-2  
15 LF Reseal failed joints in metal coping cap and reattach. [7]

**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAH

Area: 5929 SF

Age: 16

Total Repair Costs \$ 2650  
Additional Service Life 6 Yrs

Replacement Cost @ 5.25 SF \$ 31127

Total Repair Cost/ \$ 441.67 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 1556 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 0.28$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 0.44$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69		
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09		
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004046

Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAH

Area: 5929 SF

Age: 16

Flashing							
DIS-SL-DF	Unit Cost	Qty	Total Cost	DIS-SL-DF	Unit Cost	Qty	Total Cost
BF-H-1	23.37	5	\$ 116.85				
BF-H-2	9.97						
BF-H-3	30.69						
BF-M-1	4.72						
BF-M-2	4.78	356	\$ 1701.68				
BF-M-3	5.88						
BF-M-4	19.03						
DR-H-1	27.51						
DR-H-2	51.45						
DR-H-3	47.43						
DR-H-4	102.21						
DR-M-1	21.98	2	\$ 43.96				
DR-M-2	34.20						
DR-M-3	19.54						
EM-H-1	6.63						
EM-H-2	8.56						
EM-H-3	14.60						
EM-H-4	7.63						
EM-H-5	21.16						
EM-M-2	6.46						
EM-M-3	6.68						
EM-M-4	6.80						
FP-H-1	16.82						
FP-H-2	47.26						
FP-H-3	82.84						
FP-H-4	22.88						
FP-M-1	4.81						
FP-M-2	5.78						
FP-M-3	31.07						
FP-M-4	19.54						
MC-H-1	9.50						
MC-H-2	9.44						
MC-H-3	5.37						
MC-M-1	15.41						
MC-M-2	18.19	15	\$ 272.85				
MC-M-3	8.11						
MC-M-4	4.00						
MC-M-5	6.63						
PP-H-1	19.54						
PP-H-2	37.47						
PP-H-3	21.98						
PP-H-4	51.69						
Insulation:				Repair SetUp Charge =			
	0.00		NONE			\$	514

IP12\_004047

# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAI  
 Section Area: 8547

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2006				
Additional Service Life (w/repairs):	5 Year(s)			Current	Improved
Predicted Year of Replacement (w/repairs):	2011			ICI	100
				FCI	50
Cost for Repairs:	\$ 3358.00	671.60	\$/year	MCI	89
Cost for Replacement:	\$ 44871.75	2244.00	\$/year	RCI	63
					84

Adjusted Repair/Replace Ratio = 0.46      Recommendation: Repair

## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAI	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	8547
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 44871.75

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2006

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAI	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	8547
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 3358.00

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
376 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
4. BF-H-1  
4 LF Repair damaged base flashing by overlaying each localized defect with new base flashing. [4]
6. DR-M-1  
2 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [6]
7. MC-M-2  
50 LF Reseal failed joints in metal coping cap and reattach. [7]



**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAI

Area: 8547 SF

Age: 16

Total Repair Costs \$ 3358  
Additional Service Life 5 Yrs

Replacement Cost @ 5.25 SF \$ 44872

Total Repair Cost/ \$ 671.60 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 2244 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 0.30$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 0.46$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69		
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09		
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004051

Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAI

Area: 8547 SF

Age: 16

Flashing

DIS-SL-DF	Unit Cost	Qty	Total Cost
BF-H-1	23.37	4	\$ 93.48
BF-H-2	9.97		
BF-H-3	30.69		
BF-M-1	4.72		
BF-M-2	4.78	376	\$ 1797.28
BF-M-3	5.88		
BF-M-4	19.03		
DR-H-1	27.51		
DR-H-2	51.45		
DR-H-3	47.43		
DR-H-4	102.21		
DR-M-1	21.98	2	\$ 43.96
DR-M-2	34.20		
DR-M-3	19.54		
EM-H-1	6.63		
EM-H-2	8.56		
EM-H-3	14.60		
EM-H-4	7.63		
EM-H-5	21.16		
EM-M-2	6.46		
EM-M-3	6.68		
EM-M-4	6.80		
FP-H-1	16.82		
FP-H-2	47.26		
FP-H-3	82.84		
FP-H-4	22.88		
FP-M-1	4.81		
FP-M-2	5.78		
FP-M-3	31.07		
FP-M-4	19.54		
MC-H-1	9.50		
MC-H-2	9.44		
MC-H-3	5.37		
MC-M-1	15.41		
MC-M-2	18.19	50	\$ 909.50
MC-M-3	8.11		
MC-M-4	4.00		
MC-M-5	6.63		
PP-H-1	19.54		
PP-H-2	37.47		
PP-H-3	21.98		
PP-H-4	51.69		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	-----------	-----	------------

Insulation:

0.00

NONE

Repair SetUp Charge =

\$

514

IP12\_004052

# Maintenance, Repair & Replacement Analysis

Building: 9BSE-A - Administration Building  
 Section: 9BSEAI  
 Section Area: 8547

Area Cost Index: \$1.00  
 Roof Replacement Cost: \$5.25 per SF  
 Insulation Replacement Cost: \$8.00 per SF

Originally Constructed/Last Replaced: 1985  
 Current Age: 16 Year(s)

Visual Inspection Date: 5/17/2001  
 Insulation Inspection Date: -----

Predicted Year of Replacement (w/o repairs):	2006				
Additional Service Life (w/repairs):	5 Year(s)			Current	Improved
Predicted Year of Replacement (w/repairs):	2011			ICI	100
				FCI	50
Cost for Repairs:	\$ 3358.00	671.60	\$/year	MCI	89
Cost for Replacement:	\$ 44871.75	2244.00	\$/year	RCI	63
					84

Adjusted Repair/Replace Ratio = 0.46

Recommendation: Repair

## Corrective Action Requirement Sheet

## Roof Replacement

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAI	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	8547
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est Replace Cost:	\$ 44871.75

**CORRECTIVE ACTION RECOMMENDED:** Total replacement of roof in 2006

**JUSTIFICATION:** An economic analysis of the roof condition, including age, indicates that it is more cost effective to totally replace the roofing system, rather than perform the necessary maintenance, repair, and/or partial replacement of the roofing system.

**DESIGN CONSIDERATIONS:** The following considerations should be addressed during the design and construction phases of the replacement system:

- a. Type replacement systems could include
  - 1) bituminous built-up membrane
  - 2) single-ply membrane, such as EPDM, PVC etc.. If a ballasted system is selected, determine if the structural components can sustain the added weight (approx. 10 lbs/SF).
- b. Ensure that the roof has positive drainage slope of at least 1/4 inches per foot. Correct all areas that now contain ponded water.
- c. Remove all unnecessary roof mounted equipment.
- d. Inspect and repair or replace, as necessary, all remaining roof mounted equipment.
- e. Ensure that all roof mounted equipment and penetrations are properly installed on the roof.
- f. Live load and dead load impacts shall be taken into account in the design.
- g. Until the replacement roof is installed, accomplish temporary repairs to ensure that the roof remains leak free.

## Corrective Action Requirement Sheet

## Major Repair

(Note: Attach a copy of this form, along with a copy of the Roof Inspection Worksheet to DA Form 4283)

Agency/Inst.:	IPP - Intermountain Power Project	Facility No:	S1430
Bldg No./Sec:	9BSE-A 9BSEAI	Bldg Name:	Administration Building
Bldg Use:	Administration	Inspection Date:	May/2001
Membrane:	BUR: Asphalt	Area (SF):	8547
Surfacing:	AGG: Pea Gravel	Age (Yrs):	16
Vapor Ret:	UNKNOWN	Deck Type:	STEEL
Insulation:	EXPANDED POLYSTYRENE	Est. Repair Cost:	\$ 3358.00

CORRECTIVE ACTION RECOMMENDED: Maintenance, Repair and/or Partial Replacement

JUSTIFICATION: An economic analysis of the roof condition, including age, indicates that it is more cost effective to accomplish the necessary maintenance, repairs and/or partial replacement of the roofing components rather than replace the roofing system. Therefore, accomplish the following actions for the above roof section.

[Note: numbers refer to identification numbers of distresses corresponding with the Roof Inspection Worksheet]

3. BF-M-2  
376 LF Prime exposed and deteriorated base flashing and coat with heavy bodied asphalt coating. [3]
4. BF-H-1  
4 LF Repair damaged base flashing by overlaying each localized defect with new base flashing. [4]
6. DR-M-1  
2 Prime and coat surface of roof drains having exposed stripping felts with heavy bodied asphalt coating. [6]
7. MC-M-2  
50 LF Reseal failed joints in metal coping cap and reattach. [7]

**Economic Evaluation Worksheet for a Built-Up Roofing System**

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAI

Area: 8547 SF

Age: 16

Total Repair Costs \$ 3358  
Additional Service Life 5 Yrs

Replacement Cost @ 5.25 SF \$ 44872

Total Repair Cost/ \$ 671.60 \$/Yr  
Additional Service Life

Replacement Cost/20 Years \$ 2244 \$/Yr

**Cost Analysis**

Generated: Jun/27/2001

$$\text{Ratio} = \frac{\text{Repair Cost/Year}}{\text{Replace Cost/Year}} = 0.30$$

Adjusted  
Ratio

Recommended  
Action

$$\text{Adjusted Ratio} = \text{Ratio} + (0.01 * \text{Age}) = 0.46$$

0 - 0.8  
0.8 - 1.2  
> 1.2

Repair  
Marginal  
Replace

**Membrane**

DIS-SL-DF	Unit Cost	Qty	Total Cost
BL-H-1	25.37		
BL-M-1	2.08		
DV-H-1	37.48		
DV-M-1	5.69		
DV-M-2	24.06		
DV-M-3	5.69		
EQ-H-1	87.78		
EQ-H-2	156.73		
EQ-M-1	311.06		
EQ-M-2	156.73		
HL-H-1	24.39		
PA-H-1	13.43		
PA-M-1	13.43		
RG-H-1	20.90		
RG-H-2	25.37		
RG-M-1	2.09		
SL-H-1	18.94		
SP-H-1	16.85		
SR-H-1	6.05		
SR-H-2	4.31		
SR-H-3	4.14		
SR-H-4	25.44		
SR-M-1	2.09		
SR-M-2	2.41		
SR-M-3	1.17		
SR-M-4	3.54		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	--------------	-----	---------------

IP12\_004056

Economic Evaluation Worksheet for a Built-Up Roofing System

Agency/Inst: IPP - Intermountain Power Project

Building/Section: 9BSE-A  
9BSEAI

Area: 8547 SF

Age: 16

Flashing

DIS-SL-DF	Unit Cost	Qty	Total Cost
BF-H-1	23.37	4	\$ 93.48
BF-H-2	9.97		
BF-H-3	30.69		
BF-M-1	4.72		
BF-M-2	4.78	376	\$ 1797.28
BF-M-3	5.88		
BF-M-4	19.03		
DR-H-1	27.51		
DR-H-2	51.45		
DR-H-3	47.43		
DR-H-4	102.21		
DR-M-1	21.98	2	\$ 43.96
DR-M-2	34.20		
DR-M-3	19.54		
EM-H-1	6.63		
EM-H-2	8.56		
EM-H-3	14.60		
EM-H-4	7.63		
EM-H-5	21.16		
EM-M-2	6.46		
EM-M-3	6.68		
EM-M-4	6.80		
FP-H-1	16.82		
FP-H-2	47.26		
FP-H-3	82.84		
FP-H-4	22.88		
FP-M-1	4.81		
FP-M-2	5.78		
FP-M-3	31.07		
FP-M-4	19.54		
MC-H-1	9.50		
MC-H-2	9.44		
MC-H-3	5.37		
MC-M-1	15.41		
MC-M-2	18.19	50	\$ 909.50
MC-M-3	8.11		
MC-M-4	4.00		
MC-M-5	6.63		
PP-H-1	19.54		
PP-H-2	37.47		
PP-H-3	21.98		
PP-H-4	51.69		

DIS-SL-DF	Unit Cost	Qty	Total Cost
-----------	-----------	-----	------------

Insulation:

0.00

NONE

Repair SetUp Charge =

\$ 514

IP12\_004057